



## Robert Bosch Tool Recalls Grinders Due to Risk of Burns

470

Print

The grinder can overheat while in use, causing the brush covers to melt and expose the end of the brush holder.

Recall date: May 11, 2016

Recall number: 16-158

### Name of product:

Bosch small angle grinders

### Hazard:

The grinder can overheat while in use, causing the brush covers to melt and expose the end of the brush holder, posing a risk of burns to the consumer.

Remedy:

[Repair](#)

### Consumer Contact:

Robert Bosch Tool toll-free at 844-552-6724 Monday through Friday between 7 a.m. and 7 p.m. CT, or online at [www.BoschTools.com](http://www.BoschTools.com) and then click on Important Product Recalls at the bottom of the page for more information.

[Report an Incident Involving this Product](#)

### In conjunction with



### Units

About 91,000 (in addition, 18,000 were sold in Canada)

### Description

This recall involves Bosch 1380 Slim small, 4.5-inch angle grinders with date codes 502 through 511. The model number and date codes are located on the name plate affixed to the underside of the grinder. The grinders are blue and silver with a black label and black and red control buttons. "BOSCH" is printed in red on the side of the product.

### Incidents/Injuries

The firm has received four reports of the grinders overheating. No injuries have been reported.

### Remedy

Consumers should immediately stop using the recalled grinders and contact the firm to obtain a free repair.

